

**In-Vehicle / In-App Communication  
Service Action Notification-Reminder  
25 Mar 2026**

Title	Text	Short Text	Pop-Up
<p>Service Action: Exhaust Gas Turbocharger Oil Return Line Bolt</p>	<p>It was determined that the oil return line for the turbo charger was installed with a bolt of the wrong size. The bolt for the oil return line needs to be replaced.</p> <p>Contact authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: <a href="http://bmwusa.com/dealer">bmwusa.com/dealer</a>.</p>	<p>Service Action: Exhaust Gas Turbocharger Oil Return Line Bolt. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: <a href="http://bmwusa.com/dealer">bmwusa.com/dealer</a></p>	<p>Service Action: Exhaust Gas Turbocharger Oil Return Line Bolt. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: <a href="http://bmwusa.com/dealer">bmwusa.com/dealer</a></p>