



Service Bulletin

Bulletin No.: PIT6244A
Date: March, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - 4WD Indicator Appears To Be Missing From IPC

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2024 - 2026		All	All	All	All
Chevrolet	Silverado 2500	2024 - 2026		All	All	All	All
Chevrolet	Silverado 3500	2024 - 2026		All	All	All	All
GMC	Sierra 1500	2024 - 2026		All	All	All	All
GMC	Sierra 2500	2024 - 2026		All	All	All	All
GMC	Sierra 3500	2024 - 2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	With Base IPC RPO UDC
Condition	Some customers may comment that the four-wheel drive indicator is missing from the IPC / DIC.
Cause	The cause of this condition could be a misunderstanding that the left lower corner of the DIC has a dual purpose, which displays the rear passenger seat belt indicators and the four-wheel drive indicator (with compass if equipped), shown below.



6737171



6741782

Correction

None. It is normal operation that when the vehicle is first started, the left lower corner of the DIC will display the rear seat belt reminder and then after the vehicle is driven a short distance it will change and display the four wheel-drive indicator. While the four-wheel drive indicator is displayed it will flash during transfer case shifting (2WD, 4WD, Auto, etc.) to indicate the shift is occurring.

Version	2
Modified	09/25/2024 - Created. 03/23/2026 - Updated to add 2026 model years

