



Service Bulletin

Bulletin No.: PIP6106

Date: March, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip LSD Engine Potential Coolant Loss Water Pump Area

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2026		All	All	1.5 LSD	All
GMC	Terrain	2026		All	All	1.5 LSD	All


Involved Region or Country	North America
Condition	Potential coolant leak in water pump area.
Cause	Please review the diagnostic tips.

Correction

Dealers may encounter a coolant leak in the water pump housing and/or pump area. At this time to avoid unnecessary part replacement please review the following diagnostic tips:

* Due to the amount of potential leak areas in the water pump and housing area, it is best to add tracer dye to the cooling system and validate the leak under pressure hot engine and cold engine.

* Please review the following graphic for potential leak point areas.



7104640

Version	1
Modified	03/26/2026 - Created on

