



Service Bulletin

Bulletin No.: PIT6416A

Date: March, 2026

PRELIMINARY INFORMATION

Subject: Glove Box Door Does Not Fit Properly

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2024-2026		All	All	All	All

Involved Region or Country	North America
Condition	It may be noticed that the glove box/Instrument panel compartment door does not fit flush to the compartment. It may also be noticed that excessive effort is required to close the glove box door.
Cause	Fit concern.

Correction

Do Not attempt any repairs at this time.

Please advise the customer that engineering is currently working on a design improvement.

A bulletin will be released when a repair procedure is available.

Version	2
Modified	07/30/2025 - Created. 03/27/26- Updated to update model years.

