

# Last Year Claim Paid Top 10 Warranty Components and Action

Overarching Topic	Cause & Measures taken
Wheel Nut Guard	Main Culprit (PFP): ACC 5903
Coolant Level Sensor	PFP: 0693316-000 & 0696622-000 – “Low coolant” pop-up occurring despite full coolant overflow tank. Does not meet FRACAS criteria.
ABS Wiring Harness	Main Culprit (PFP): A66-07848-300 ABS fault codes, system dropping out, cruise control dropping out. Production containment 9/ 2024. Working on LICA.
Wheel Stud	Main Culprit (PFP): CM 10036462
A/ C Compressor	A/ C inop. Currently investigating topic (Quality FQT topic)
Front Shock Absorbers	Main Culprit (PFP): 10-14339-000 has been superseded in February 2023.
Right Heated Mirror	Main Culprit (PFP): A22-78606-005 has been superseded in February 2025.
Heater Return Pipe	Crack at welding point between mounting tab and pipe. New design direction to switch to nylon. Design work completion targeting Q1 2026.
Wheel Speed Sensor	Main Culprit (PFP): WAB 441 032 381 0. ABS light on, no issue with harness or routing. Working on LICA.
LV Battery	Main Culprit (PFP): A66-06013-002, No start/ hard crank, R&R batteries. No investigations opened, not a systematic issue with AGM battery PFP.