

# Preview Solution CBR-2570-1

## EBS - Electro-Pneumatic Module - Signal Compare Failure DTC C109562 - VN (4) - AN (4) - PR

Published 23 March 2026

### Valid For


Mack Chassis - AN (4), PR


Volvo Chassis - VN (4)

Model Year - 2024 to Current

The purpose of this CBR is to help address fault code C109562 for the EBS - Electro-Pneumatic Module.

On certain chassis with an active C109562 there have been reports of electrical pin locations within the EPM connectors being in the incorrect pin designations. Please refer to the vehicle schematic to ensure pin to pin check from EBS (Electronic Brake System) module X1 connector to affected EPM (Electro Pneumatic Module) are correct. Examples below.





### Related links and attachments

No links or attachments available



### Share

to others that might find it helpful



### Feedback

[Give feedback](#)

to help improve the content of this article