

2026 MY Bronco

Accessory Protocol Interface Module - SYNC

SYNC-26.2.7.6

Safety Recall 26S09

Accessory Protocol Interface Module

To view your past software updates, or if you've had multiple updates completed recently, visit: <https://www.ford.com/support/software-updates>

1

SYNC-26.2.7.6

"This software update contains the following key changes:

- On your vehicle, it may be possible to experience an unexpected blank infotainment screen due to the APIM (Accessory Protocol Interface Module) temporarily shutting down when detecting high cabin temperatures. When the APIM temporary shutdown occurs, your vehicle will not display the rearview camera image while in reverse. A rearview camera image that does not display while in reverse gear can reduce your view of what is behind the vehicle, increasing the risk of a crash. We have updated the software on your APIM to address this concern. This completes Safety Recall 26S09. No further action is required."