

---

<b>Reference</b>	SSM000031
<b>Models</b>	Defender / L663 2026 → Onwards Discovery / L462 2026 → Onwards New Range Rover / L460 2026 → Onwards New Range Rover Sport / L461 2026 → Onwards
<b>Title</b>	DTC C1D18-55 Set in Tire Pressure Monitor Module (TPM) During Pre-Delivery Inspection (PDI)
<b>Category</b>	Electrical
<b>Last modified</b>	31-Mar-2026 09:59:00

---

**Content**

Title: DTC C1D18-55 Set in Tire Pressure Monitor Module b(TPM) During Pre-Delivery Inspection (PDI)

**Model / Model Year / Derivative**

Range Rover / 26MY onwards / All

Range Rover Sport / 26MY onwards / All

Defender / 26MY onwards / All

Discovery / 26MY onwards / All

**Situation:**

JLR Engineering investigations have identified that Diagnostic Trouble Code (DTC) C1D18-55 is set in the TPM during PDI and cannot be cleared using TOPIx Cloud.

**Cause:**

DTC C1D18-55 was introduced to the above vehicle models at 26MY. The DTC is generated where the wheel locations have yet to be stored in the TPM and will remain until the vehicle has completed a drive cycle of 10 minutes continuous driving above 20 km/h (14 mph).

**Action:**

Refer to the service information below.

**Service Information:**

No action is required as the DTC will automatically clear during the PDI drive cycle and the tire pressures will display on the Instrument Panel Cluster.

(Ref: 000410205 / 8849)

anBhdHRknM7MjAyNi0wMy0zMVQxMjpyMDo0Nj41MzFaOzEwOC4yOS43NS4xMDQ7