

D093 – V8 DOOR DECALS NOT INSTALLED UPDATE PRIOR TO SALE CAMPAIGN



AFFECTED MODELS	26MY Range Rover Sport
VOLUME AFFECTED	71 USA 35 CAN
REPAIR	A concern has been identified on certain vehicles where the front door V8 decals were not installed at the factory. Retailers are to install the missing or affected vehicles.
REPAIR TIME	0.2 hr + DIDO
CAMPAIGN LAUNCH	Launched on Mar 4th, 2026
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is completed. All affected VINs are flagged in TOPIX, the warranty portal and retailer inventory reports are available in BBSS. Refer to Customer Service Parts Operations Bulletins 252603.017 - USA, and JLRC5-2603.02 (CAN) for details of V8 decals that have been pre-shipped to your retailer.