

WTB3 Workshop Campaign - Applying corrosion protection to the door

WTB3 Workshop Campaign - Applying corrosion protection to the door

ID Number	WTB3
Model(s)	Macan (95B)
Model Year(s)	2016 - 2023
Number of Affected Vehicles	92
VIN List	Attached below
Issue Description	There is a possibility that not enough corrosion protection wax was applied on the affected vehicles. If this is the case, corrosion can occur on the lower door fold over the service life, depending on weather conditions. To prevent this, corrosion protection must be subsequently applied to the door on the affected vehicles
What should Porsche Centers do?	Please arrange for the measure to be carried out on affected vehicles as soon as possible. As of the time of this posting (3/3/26) the remedy is immediately available.
Parts Status	Status 1 - Order via PPL as needed.
TI	WTB3

Required parts

V04015001AG	Cavity preservative	0.1-0.4 piece(s)
-------------	---------------------	------------------

Warranty processing

Validity:

WTB3 Workshop Campaign - Applying corrosion protection to the door

The present workshop campaign is carried out by the date maintained in PCSS and then closed.

Please note that warranty claims can only be processed up to this date.

Scope 1-4: Apply corrosion protection to one door

Damage Code	WTB3 66 000
Repair Code	1
Labor time	20 TU

Scope 5-9: Apply corrosion protection to two doors

Damage Code	WTB3 66 000
Repair Code	1
Labor time	36 TU

Scope 10: Apply corrosion protection to all four doors

Damage Code	WTB3 66 000
Repair Code	1
Labor time	72 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WTB3_2026-03-03_V4.xlsx](#)