

WSP4 Workshop Campaign - Replacing rear right drive shaft

WSP4 Workshop Campaign - Replacing rear right drive shaft

ID Number	WSP4
Model(s)	Macan 4S (XABDC1)
Model Year(s)	2025
Number of Affected Vehicles	4
VIN List	Attached Below
Issue Description	It is possible that the rear right drive shaft on the affected vehicles does not meet the required specifications. As a result, oil leakage may occur on the rear axle differential. To prevent this, the rear right drive shaft must be replaced on the affected vehicles.
What should Porsche Centers do?	Please arrange for the measure to be carried out on affected vehicles as soon as possible. As of the time of this posting (3/9/26) the remedy is immediately available.
Parts Status	Status 1 - Order via PPL as needed
TI	WSP4

Attachments

1. [VIN_List_Report_WSP4_2026-03-09_V4.xlsx](#)