

# 43-083: Exhaust Stack Assembly Isolators

3/20/2026

 [Edit](#)  [Clone](#)

43-083

## Subject

Exhaust Stack Assembly Isolators

## Whats New Abstract

Early wear of the polyurethane exhaust stack isolators may occur on certain Peterbilt chassis due to excessive heat.

## Condition

Customers may notice wear of the exhaust stack assembly isolators. A new, high temperature isolator is available for replacement.

## Chassis Affected

Vehicle model year 2024-2026 Model 567 / 579 / 589 chassis equipped with polyurethane exhaust stack isolators

## Action

### Fix-as-Fail

If a chassis comes into your dealership with exhaust stack isolators that appear degraded due to excessive heat, follow the procedures in the Attachments section to remove and replace them with new, high temperature isolators.

## Warranty

Starting from 03/20/2026, through Standard Warranty or any applicable active Extended Warranty, Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:

- **0.3 hours** of labor to remove and replace degraded right hand (RH) or left-hand (LH) exhaust stack isolators with new high temperature isolators. Use Recommended Repair Code **43-083A**.
- **0.6 hours** of labor to remove and replace degraded right hand (RH) and left-hand (LH) exhaust stack isolators with new high temperature isolators (dual stack only). Use Recommended Repair Code **43-083B**.
- File an additional claim for extraordinary circumstances. A Recommended Repair for standard

labor must be filed first.

**Take-Off Parts Disposition:**


- Destroy 30 days after claim is paid

PRWS CLAIM CODING			
<b>Campaign Code</b>	43-083	<b>Campaign Type</b>	Field Repair
<b>Claim Category</b>	Truck	<b>Repair Type</b>	Fix-As-Fail
<b>Customer Concern Code</b>	169 – Worn	<b>Causal Code</b>	44 – Worn
<b>Corrective Action Code</b>	03 – Replace with New	<b>Responsibility Code</b>	CAMP-Campaign
<b>Failure Location</b>	043-003-013	<b>Causal Part</b>	M13-6009
<b>Supplier Code</b>	N/A	<b>SRT Code</b>	<p><b>B26-15A</b>  <b>0.3 hours</b>                      Exhaust Stack Assembly LH or RH Isolators per bulletin procedure</p> <p><b>B26-15B</b>  <b>0.6 hours</b>                      Exhaust Stack Assembly LH and RH Isolators per bulletin procedure</p>

Parts

Quantity	Part Number	Description
3 (single stack)	M13-6012	Bushing – Anti
6 (dual stack)		Vibration MT

Procedure

	<b>WARNING!</b>
<p><b>Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps</b></p>	

**before performing any work and follow all dealership safety procedures or precautions. Failure to comply may result in death, personal injury, or property damage.**

Please see the Attachments section below for procedures on inspecting, removing degraded exhaust stack isolators, and replacing them with new, high temperature isolators.

## Attachments

---

[43-083 Exhaust Stack Assembly Isolators Repair Procedure](#)