

## D089 – CAR CONFIGURATION FILE (CCF) UPDATE CUSTOMER SATISFACTION CAMPAIGN



AFFECTED MODELS	26MY Defender OCTA vehicles
VOLUME AFFECTED	787 USA 102 CAN
REPAIR	On certain vehicles where the engine coolant temperature amber warning is not enabled and not displayed on the instrument panel cluster, a Car Configuration File (CCF) update is required; the engine coolant temperature amber warning will then be displayed on the instrument panel cluster when required.
REPAIR TIME	Up to 0.3 hr + DIDO
CAMPAIGN LAUNCH	Launched on Mar 5th, 2026
NOTES	Retailers are required to hold all affected vehicles in their inventory from sale until the repair is completed. All affected VIN are flagged in TOPIX, the warranty portal and BBSS. Please ensure all affected sold vehicles are repaired at the next earliest service visit.