

## D061 – TURBOCHARGER COOLANT FEED/RETURN PIPE LEAKS OWNER NOTIFIED SERVICE ACTION



AFFECTED MODELS	23-24MY Range Rover, Range Rover Sport; Defender vehicles equipped with the INGENIUM I6 3.0L Petrol Engine
VOLUME AFFECTED	27402 USA 2696 CAN
REPAIR	A concern has been identified on certain vehicles where coolant may leak from the turbocharger coolant hose O-rings, resulting in engine coolant escaping into the engine compartment and subsequent illumination of the low coolant warning indicator on the instrument cluster. Replacement coolant hose O-rings are required.
REPAIR TIME	0.9 hr + DIDO
CAMPAIGN LAUNCH	Launched on Feb 13th, 2026
NOTES	<p>All affected VINs are flagged in TOPlx, the warranty portal and BBSS. Please ensure all affected vehicles are completed at the next earliest service visit and unsold vehicles repaired before sale.</p> <p>Owners will be notified by mail requesting they make repair service appointments.</p> <p>Refer to Customer Service Parts Operations Bulletins 252602.032 - USA, and JLRCS-2602.05 (CAN) published February 12th, 2026, for details of Turbocharger O-rings that have been pre-shipped to each retailer.</p>