

## D098 – DEFENDER 110 3RD ROW SEATBELT MOUNTING STUD – INCORRECT SPECIFICATION VEHICLE QUARANTINE



AFFECTED MODELS	26MY Defender 110 equipped with 3rd row seating
VOLUME AFFECTED	328 US 137 CAN
CONCERN	The 3rd row seatbelt outboard lap belt anchorage stud on certain vehicles may not be consistently manufactured to the as-specified ISO strength grade and may not meet JLR's design specification. Vehicles will require replacement on the LH and RH 3rd row seat belt anchor brackets.
REPAIR TIME	1.5 hrs + DIDO
CAMPAIGN LAUNCH	Retailers were notified via quarantine bulletin on March 3rd, 2026. Repair bulletin is in preparation and will be published under a UPS campaign bulletin when parts are available. Target launch is March 24 <sup>th</sup> , 2026.
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is completed. All affected VINs are flagged in TOPIX, the warranty portal and retailer inventory reports are available in BBSS.