

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
S4	2011 – 2013	All	DL501 transmission
S5 Cabriolet	2011 2013		
A5 Cabriolet	2012		
A4, S5, RS 5, RS 5 Cabriolet, S6, and S7	2013		

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add Model Year, Model)
1	01/22/2018	Initial publication

Customer states:

- There is no direct customer complaint.

Workshop findings:

- After replacing the mechatronic unit, the transmission, or updating the transmission control module (TCM) software there is a noticeably longer delay when switching from reverse gear to drive.

Technical Background

Due to a change in the latest TCM software the change of direction takes longer.

Production Solution

Not applicable.

Service

This characteristic is deliberate and normal.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2050138**) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2026 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.