

 Connection offline

Technical Service Bulletin

93 Q4 drive system fault P164700/P060C00

Transaction No.: **2080615/2**

Release date: Mar 27, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2024 – 2026	All	V7A, V7B, or V7C, or V7E

REVISION HISTORY

Revision	Date	Purpose
2	-	Revised header (Added PR code)
1	01/14/2026	Initial publication

Customer states:

Drive system fault in instrument cluster.

Workshop findings:

The following DTCs are logged in diagnostic address 0001 (drive system control unit):

- **P164700** with symptom 44180 and/or 44181.

and

- **P060C00** with symptom 43863.

or

- **P060C00** with symptom 32326.

Technical Background

Software robustness.

Production Solution

06/21/2024

Service

This TSB replaces Pending Service Solution (PSS) TSB 2074415: *93 PSS Q4 drive system fault P164700/P060C00*.

Please check whether TSB 2080398, *00 Combined software update ID.S 5.4.3 for Audi Q4* is shown for the vehicle. If so, please perform the software update described.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9370		
Damage Code:	0040		
Labor Operations:	GFF	0150 0060	Time stated on the diagnostic protocol
	GFF	0150 0010	See SRT with associated operations
Claim Comment:	As per TSB 2080615/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2080615**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.