



Mitsubishi Motors North America Inc.

Warranty Bulletin

SUBJECT:

**MY26 Outlander with "Check Engine"
Light On W/ P2096 or P0128 codes**

USA

Canada

P. Rico

Mexico

X

X

X

Issue Date

March 20th, 2026

Bulletin Number

WB2026-007

Subject:

MY26 Outlander equipped with a 4B40 engine exhibits symptoms related to either TSB-26-14-001 or TSB-26-13-001. Please refer to the instructions referenced in the table below.

Submit a warranty claim with the defined language on a warranty claim using the labor operation code provided below.

<i>Labor Operation Code</i>	<i>16850000</i>
<i>Labor Time</i>	<i>0.3 Hrs</i>
<i>Complaint</i>	<i>"Check Engine" Light is Illuminated</i>
<i>Cause</i>	<i>Incorrect configuration of software with no drivability concern.</i>
<i>Remedy</i>	<i>MMNA is investigating the concern and will share more information once available.</i>

No part replacements are necessary, please clear the code and advise the customer that MMNA is investigating the concern.

If the above resolution does not satisfy the customer, loaner or rental reimbursement expense may be available with District Aftersales Manager approval.

If you have any questions, please call the Warranty Information Line @ 1.800.380.2324. You may also email us at WarrantyWebHotline@mmsa.com.

MMNA WARRANTY DEPARTMENT

3/20/2026

© Copyright Mitsubishi Motors North America, Inc.

Page 1/1