

2025 MY Maverick

Powertrain Control Module - PCM

PT-26.12.1

Safety Recall 25C69

Secondary Onboard Diagnostic Module C

To view your past software updates, or if you've had multiple updates completed recently, visit: <https://www.ford.com/support/software-updates>

1

PT-26.12.1

"This software update contains the following key changes:

- On your vehicle, the Integrated Park Module (IPM) may not properly engage the park pawl, preventing the vehicle from locking into Park when Park (P) is selected. If this condition occurs, a wrench light and shift system fault message will be displayed in the instrument panel cluster. Additionally, the vehicle's Electronic Parking Brake (EPB) will automatically apply. If the park pawl is not properly engaged and the Electronic Parking Brake (EPB) is not applied, your vehicle may experience a roll-in-park, increasing the risk of a crash. We have updated your Secondary Onboard Diagnostic Module C (SOBDMC) to correct this condition. This completes Safety Recall 25C69. No further action is required."