



# Service Bulletin

Bulletin No.: PIT6509

Date: April, 2026

## PRELIMINARY INFORMATION

**Subject: Changing Units Setting is Missing under System Menu**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2025		All	All	All	All
Chevrolet	Traverse New	2024 - 2025		All	All	All	All
GMC	Acadia	2024 - 2025		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO)</b>	IVE
<b>Condition</b>	A customer may comment that the units setting is missing from system menu after a radio software update.
<b>Cause</b>	Engineering is currently investigating.

### Correction

Do not replace any part for this issue.

Engineering is currently investigating.

In the meantime, please advise customer they may continue to drive the vehicle.

The PI will be updated or replaced with TSB once a determination has been made.

<b>Version</b>	1
<b>Modified</b>	04/23/2026 - Created On

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.