

Top Routing and Clipping Defects - A/C Harness

Topic Background

- A/C harness rubbing on compressor

Progress Updates

- The connector was rubbing against the compressor due to missing support for wiring routing.

Topic Resolution Info

- Shopcall was created to add a new routing with a bracket and zip tie to secure the connector and prevent chafing.

