

SS 305 TBB EFX AC Upper bracket TBB 130987 replaced with TBB 248310

Applicable Vehicles

M06 through M2026 EFX

Symptoms

TBB 130987 weld cracks

Solution

If part TBB 130987 exhibits weld cracks, replace with TBB 248310 using installation procedures in installation diagram TBB 248369. This Diagram can be found in ESP.

Labels :

Transit-Liner

Add tags



0 Kudos

Comment