

# SS 306 TBB HDX DEF Header Service Replacement Additional Parts

## **Applicable Vehicles**


TBB HDX

## **Symptoms**

DEF Header Failure replacement

## **Issue**

There are no longer SSI DEF Header replacement parts. If the vehicle came equipped with an SSI DEF Header, and that SSI DEF Header has failed, then a replacement KUS DEF Header 04 37614 000 must be used. The replacement requires some additional parts and re routing of DEF Pump Supply Coolant line. Refer below for how item 20 and 22 is routed.



## Solution

Order additional parts

Pump Supply Coolant line. Refer below item 20 and 22 is installed.

Note, parts would need to be ordered.

TBB 248554 Formed hose Silicone

TBB 248552 Formed hose BS 5/8 ID

TBB 248782 Pipe

Hose Clamps TBB 61190163 (4)

Labels :

Transit-Liner

Add tags



0 Kudos

Comment

