

 Connection offline

Technical Service Bulletin

Transaction No.: **2081427/2**

97 Thermal management 00C5: MIL on, P1A7B00 Control module 1 for radiator fan, incorrect component installed

Release date: Apr 30, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A5, S5 (FU), Q5, Q5 Sportback, SQ5, and SQ5 Sportback (GU)	2025 - 2026	All	Not applicable
A6 (FN)	2026		

REVISION HISTORY

Revision	Date	Purpose
2	-	Revised <i>Service</i> (adjusted instruction)
1	03/20/2026	Initial publication

Customer states:

- Check engine light (MIL) on.

and/or

- Unusual behavior of radiator fan - long run-on or runs at full load.

Workshop findings:

The following event memory entry is logged in the thermal management control unit 00C5:

- **P1A7B00** - Control module 1 for radiator fan, incorrect component installed.

Technical Background

Under analysis.

Production Solution

Not applicable.

Service

If the scenario described above occurs, please check the configuration of HCP4 (J519/onboard supply control unit).

Warranty

Claim Type:	<ul style="list-style-type: none"> If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9710		
Damage Code:	0040		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2081427/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2081427**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.