

### Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A3, S3, and RS3	2025	All	Data Bus OBD Interface 0019: Software version 2086 PR Code KA2 Reversing Camera

### Customer states:

The reversing camera view cannot be changed via the MMI. The rear corner view cannot be activated.

Please compare the complaint with the attached image.



Figure 1. Reversing Camera MMI Selection

### Workshop findings:

The complaint can be reproduced.

### Technical Background

Software issue. The soft keys shown have no function and should not appear in the reversing camera view.

#### NOTICE

There are no issues with the reversing camera system. All functions offered by Audi are available.

### Production Solution

From software version 2091 in diagnostic interface (diagnostic address 0019) in week 48/2024

### Service

This TSB replaces Pending Service Solution (PSS) TSB 2076961, *91 PSS Reversing camera - rear corner view cannot be activated via the MMI*.

A software update has been prepared to repair this issue. This software update also contains updates for further control units and is being published as a combined software update.

Please check whether TSB 2081007, *91 Software update for MMI, OCU and gateway for MIB3 vehicles (version MQB ST3BP without AED)* is shown in the **Technical Service Handbook** area in ElsaPro. Follow the instructions included.

A separate TSB "Software update for MMI, connectivity box for MIB3 vehicles (version MQB ST3BP +AED)" is being prepared for vehicles which additionally require a software update of the Android control unit. This will also be published once preparations are complete.

Independent dealerships without access to ElsaPro can request this information via the block exemption helpline.

## Warranty

This repair should be invoiced via the corresponding TSB that has been published.

Please refer to the description provided in the corresponding TSB.

## Additional Information

All part and service references provided in this TSB (**2081570**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.