

Condition

Model(s)	Year(s)	Vehicle Specific Equipment
A3, S3, and RS 3	2025	With PR Code 1N3

Customer states:

- The steering wheel pulsates/vibrates when parking or driving around tight corners (multi-story car park, roundabout, etc.). An example video can be viewed at <https://audi-external.kzoplatform.com/misc/sl/CtTgC3X3> or by scanning the QR code below.



Figure 1. Scan the QR code to view an example video.

Workshop findings:

- The complaint can be attributed to the steering/ESP unit.

Technical Background

This is a software-related comfort complaint that can occur intermittently under certain circumstances (vehicle load, speed, surface, etc.).

Production Solution

Outstanding.

Service

- First check whether TSB 2081760, *45 ABS/ESP intervenes early at low speeds* applies to the affected vehicle.

If yes:

- Please work through TSB 2081760 and then check whether the complaint still occurs. If the complaint still occurs, postpone the repair to the steering rack.

If no:

- Please postpone the repair to the steering rack as there is currently no effective repair for the complaint described by the customer.

1. Diagnose the vehicle according to the instructions above. If the customer's vehicle condition matches the condition listed in the *Technical Background* of this PSS TSB, explain to the customer that a solution is expected to be available from the third quarter 2026 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS database via the Pending Service Solutions (PSS) link found in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

A technical solution is currently being implemented.

Note: The target date communicated here is based on planning and is not binding. During the validation, technical and regulatory approval of measures, there may be delays or hindrances in providing the measure throughout the entire process. This must be considered accordingly when communicating with customers.

Warranty

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2081590**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.