



TECHNICAL SERVICE INFORMATION BULLETIN

TSIB 26-01		May 5, 2026
TO:	MCI Operators	
TITLE:	MCC EcoTemp T35-1581 V1.04 Software Upgrade.	
APPLICABILITY:	All MCI Coaches using MCC EcoTemp T35-1581 / V1.04 ECU # 07-10-0090.	

Some coaches using MCC HVAC Eco-Tempo ECU # 07-10-009 software T35-1581 / V1.04 may be experiencing random fault codes due to MCC software errors. To correct these issues, MCI and MCC engineering release HVAC Eco-Temp ECU # 1143549 software T35-1581 / V4.06. Production Coaches moving forward will have the new Eco-Temp ECU # 1143549 software T35-1581 / V4.06.

All MCI Coaches experiencing this issue using MCC EcoTemp T35-1581 / V1.04 ECU # 07-10-0090 should upload T35-1581 / V4.06 software into the existing Eco-Temp controller. Update the Eco-Temp controller decal using MCI # 1141747.

BCC SW#: T35-1581 MCI V4.06.hex

Customers are guided to contact their Technical Service Manager for a copy of the software.