

<b>REFERENCE:</b>	<b>TSB:</b> 08-137-26 REV. C <b>GROUP:</b> 08 - Electircal	<b>Date:</b>	May 1, 2026	<b>REVISION:</b>	08-137-26 REV. B
<b>VEHICLES AFFECTED:</b>	<b>2026 (LB) Dodge Charger</b> <b>This bulletin applies to vehicles built on or before March 09, 2026 (MDH 0309XX) equipped with a 3.0L Twin Turbo Sixpack HO ESS (Sales Code EFC).</b>			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH <b>NOTE: This bulletin applies to the North America markets.</b>	
<b>CUSTOMER SYMPTOM:</b>	<b>Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):</b> <ul style="list-style-type: none"> <li>• P2096-00 - Downstream Fuel Trim System 1 Lean.</li> <li>• P2097-00 - Downstream Fuel Trim System 1 Rich.</li> <li>• P2098-00 - Downstream Fuel Trim System 2 Lean.</li> <li>• P2099-00 - Downstream Fuel Trim System 2 Rich.</li> <li>• P068A-00 - ECM Power De-Energized Performance-Too Early.</li> </ul> <b>NOTE: The above DTCs are being falsely set due to lack of robustness to the diagnostic monitor.</b>				
<b>CAUSE:</b>	ISCM software				

**This bulletin supersedes Technical Service Bulletin (TSB) 08-137-26 REV. B, date of issue April 08, 2026, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include converting this TSB to information only.**

**This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-056, date of issue March 26, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.**

**DISCUSSION:**

**\*\*The software required to perform this TSB is not available at this time.\*\***

**POLICY:**

**\*\*Information Only\*\***

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*