

**Technical Service Bulletin (TSB)**  
**Flash: Transmission Control Module (TCM) Updates**

<b>REFERENCE:</b>	<b>TSB:</b> 21-020-26 REV. C <b>GROUP:</b> 21 - Transmission and Transfer Case	<b>Date:</b>	May 1, 2026	<b>REVISION:</b>	21-020-26 REV. B
<b>VEHICLES AFFECTED:</b>	<b>2026 (LB) Dodge Charger</b> This bulletin applies to vehicles built on or before <b>March 09, 2026 (MDH 0309XX)</b> equipped with a <b>3.0L Twin Turbo Sixpack HO ESS (Sales Code EFC)</b> .			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH  <b>NOTE:</b> This bulletin applies to the North America markets.	
<b>CUSTOMER SYMPTOM:</b>	Customers must experience a <b>Malfunction Indicator Lamp (MIL) illumination</b> and the vehicle must exhibit/set one or more of the following <b>Diagnostic Trouble Codes (DTCs)</b> : <ul style="list-style-type: none"> <li>• P2096-00 - Downstream Fuel Trim System 1 Lean.</li> <li>• P2097-00 - Downstream Fuel Trim System 1 Rich.</li> <li>• P2098-00 - Downstream Fuel Trim System 2 Lean.</li> <li>• P2099-00 - Downstream Fuel Trim System 2 Rich.</li> <li>• P068A-00 - ECM Power De-Energized Performance-Too Early.</li> </ul> <b>NOTE:</b> The above DTCs are being falsely set due to lack of robustness to the diagnostic monitor.				
<b>CAUSE:</b>	TCM software				

This bulletin supersedes Technical Service Bulletin (TSB) 21-020-26 REV. B, date of issue April 08, 2026, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include converting this TSB to information only.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-056, date of issue March 26, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

**DISCUSSION:**

**\*\*The software required to perform this TSB is not available at this time.\*\***

**POLICY:**

**\*\*Information Only\*\***

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*