

GPOP - Issue Review System

Part Number: 68674147A\$, 68687686A\$, 68735491A\$, 68745166A\$

Part Description: BSCM

Issue Description: DTC C008F Calibration Not Learned remains active until the EPB Assembly Check is successfully completed at the vehicle assembly plant. This function is performed using the EPB Assembly Check Routine. Dealers must run the EPB Assembly Check Routine and confirm successful completion before replacing the EPB module, as module replacement should not be performed to address this condition. Note: Replacement modules leave supplier with C008F active.