

GPOP - Issue Review System

Part Number: 68734944A\$

Part Description: CLUSTER Instrument Panel

Issue Issue :
Description: 26MY RU - Speed Limit Warning Chimes While Driving, Cluster Message Speed Warning Exceeded, Circled Speed Limit Appears on Cluster. Cluster issue if misdiagnosed can lead to unnecessary IPC replacement. Tech Tip:
Speed warning selection (circled speed) option may appear without an owner selecting the option. This option was not an option available for US vehicles. This option can be turned off by using the wiTECH scan tool, select the Body Control Module (BCM)>Misc. Functions>Cluster Speed Limit Reset. Refer SOL S2608000020 published