

WTE1 Workshop campaign - Re-programming control unit for rear-end electronics (J393)

WTE1 Workshop campaign - Re-programming control unit for rear-end electronics

(J393)

ID Number	WTE1
Model(s)	Macan Electric
Model Years(s)	2026
Number of Affected Vehicles	2,029
VIN List	Attached below
Issue Description	<p>There is a possibility that faulty position values of the luggage compartment lid may be stored in the rear-end electronics control unit (J393) on the affected vehicles.</p> <p>As a result, the end position of the luggage compartment lid that is stored in the rear-end electronics control unit deviates from the actual mechanical position. This may result in restricted comfort function, for example due to incomplete opening of the luggage compartment lid, reduced effect of the closing aid or premature stopping of the movement sequence if the obstruction detection triggers without authorization.</p> <p>For this reason, the control unit for rear-end electronics (J393) must be re-programmed. In addition, other control units are automatically updated to a corresponding software version.</p>
What should Porsche Centers do?	<p>Please arrange for the measure to be carried out on affected vehicles as soon as possible.</p> <p>As of the time of this posting (4/10/2026) the remedy is immediately available.</p>
Parts Status	Status 0 - No parts needed to complete campaign

TI

[WTE1](#)

Required software

Porsche Tester 4 test software release 44.000.031 (or higher)

Warranty processing

Validity:

The present workshop campaign is carried out by the date ("Valid until" field) maintained in PCSS and then closed.

Please note that warranty claims can only be processed up to this date.

Scope 1-2:

Damage Code	WTE1 66 000
Repair Code	1
Labour time	76-104 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WTE1_2026-04-10.xlsx](#)