

[U 26-01-040H - Cracked Inside Rear Combination Lamp Replacement \(Camp LA19\)\\_\(posted 04.23.26\).pdf](#)

## Hyundai Motor America (HMA) has launched Limited Coverage Campaign LA19 for the Cracked Inside Rear Combination Lamp Assembly Replacement!

### **A. Affected Vehicles:**

- Certain 2026MY Tucson (NX4A) produced from 02/02/2026 – 02/20/2026

- VIN Identification: Use the 'Vehicle Information' screen in WebDCS to verify "Warranty Start Date" and ensure the vehicle is within New Vehicle Limited Warranty (NVLW), observing mileage prior to any repair work.

### **B. Campaign Description:**

Certain Tucson (NX4A) vehicles have a crack on the left-hand side of the "inside rear combination lamp assembly" due to interference with the tailgate panel. **Technical Service Bulletin (TSB) 26-01-040H** provides instructions to replace the "inside rear combination lamp assembly".

### **C. Campaign Document(s):**

#### **1. TSB 26-01-040H**

- Available on [Hyundaidealer.com](http://Hyundaidealer.com) > Service > HMA Tech Info > Campaign

### **D. Parts Ordering/Information:**

#### **1. Lamp Assembly – Rear Combination, Ctr**

- a. Parts may be ordered through the normal WebDCS ordering process.
- b. An applicable VIN will be required to order the part.

### **E. Action Required:**

1. Confirm VIN eligibility Confirm VIN eligibility for campaign via WebDCS. See 'VIN Identification' above.
2. Follow **TSB 26-01-040H** for service procedure to replace the inside rear combination lamp assembly.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America