



# Service Bulletin

Bulletin No.: PIT6514

Date: April, 2026

## PRELIMINARY INFORMATION

**Subject: BCM Setting DTC U013A**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2025 - 2026		All	All	All	All
Cadillac	Escalade ESV	2025 - 2026		All	All	All	All
Chevrolet	Suburban	2025 - 2026		All	All	All	All
Chevrolet	Tahoe	2025 - 2026		All	All	All	All
GMC	Yukon	2025 - 2026		All	All	All	All
GMC	Yukon XL	2025 - 2026		All	All	All	All

<b>Involved Region or Country</b>	Europe and Middle East
<b>Additional Options (RPO)</b>	UET
<b>Condition</b>	Dealers may find a U013A (Lost Communication with TTPM) set in the BCM during service. No warnings or customer concerns will be present. This is expected on Export vehicles not equipped with TTPM (RPO UET).
<b>Cause</b>	The causes of the condition may be software anomalies.

### Correction

If DTC U013A is set in History, it should be ignored. There will be NO customer concerns or indication to the customer that the DTC is set. No further repairs should be performed to correct this DTC as it is set falsely.

<b>Version</b>	1
<b>Modified</b>	04/30/2026 - Created on

