

Technical Journal

TITLE:

PS Rear Roof Cover - with Molding Line

| | | | |
|---------------------------------------|---|--|-----------------------------------|
| REF NO: TJ 37724.1.0 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | |
| PARTNER: 3 US 7515 Polestar | | ISSUE DATE: 2026-02-12 | STATUS DATE: 2026-02-17 |
| FUNC GROUP: 8360 | FUNC DESC: Roof hatch | Page 1 of 3 | |

Attachment

| File Name | File Size |
|----------------|-----------|
| TJ_37724_1.pdf | 0.1080 MB |

DESCRIPTION:

If customer complains that there is a visible molding line on the rear roof cover, follow advice under "Service". See attachment.

CSC Customer Symptom Codes

| Code | Description |
|------|--|
| 6D | Sun/moon/convertible roof/Glass broken/chipped/cracked/distorted |

DTC Diagnostic Trouble Codes

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|---------------|------------------|
| 814 | | | | | | | 2025-9999 | | - | 202346-999952 |

SERVICE:

Please, do not replace any parts for the symptom described in this TJ. This is a molding line and not a damage.

Warranty claim info:

No warranty claim is accepted for this TJ since it is to be used as guidance.

Technical Journal 37724.1.0

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed", use function group 8360.

To view TJ attachment continue to next page. This TJ has one attachment.

TJ 37724

