

Technical Journal

TITLE:

CDD replacement, BECM-P127900 BECM-P0AA800

REF NO: TJ 37772.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2026-04-16	STATUS DATE: 2026-04-27
FUNC GROUP: 3234	FUNC DESC: Onboard charger, high voltage	Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Modified Model Year and Structure Week range to include an end date.

If the vehicle cannot engage any gear, and both DTCs are present, follow advice under “Service”.

CSC Customer Symptom Codes

Code	Description
AJ	Driving/Poor performance/lacks power
71	Starting/Vehicle start-up is not possible

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
BECM	P0AA800	Permanent
BECM	P127900	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
814	PA	E400P01 LRDM					2025-2026		-	202447-202613
814	PB	E400P02 LRSM					2025-2026		-	202447-202613

Technical Journal 37772.2.0

SERVICE:

Confirm that all criteria specified in the “Description” section are fulfilled. Replace the CDD in accordance with VIDA instructions.

Abbreviations:

CDD - Charger and DCDC Module

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ. Please note that fault tracing is not eligible for separate reimbursement under this TJ. Any fault tracing VST OP numbers will be rejected.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
98822-2	High Voltage Battery Disconnection acc to TJ
98790-2	Battery charger, high voltage replace acc. to TJ

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect, or if the criteria specified in the “Description” section are not fully met. Use concern area “Vehicle Report Polestar” and sub concern area “Support needed Polestar”, use function group 3234.