



Service Bulletin

Bulletin No.: PIT6436D

Date: May, 2026

PRELIMINARY INFORMATION

Subject: Malfunction Indicator Lamp (MIL) DTC U0265 That May Set As Current Or Failed In History

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024		All	All	All	All
Chevrolet	Colorado	2024 - 2026		All	All	All	All
Chevrolet	Equinox EV	2024		All	All	All	All
Chevrolet	Silverado EV	2024 - 2026		All	All	All	All
GMC	Canyon	2024 - 2026		All	All	All	All
GMC	Sierra EV	2024 - 2026		All	All	All	All

Involved Region or Country	United States, Canada, Mexico and South Korea
Condition	Some customers may comment on a Malfunction Indicator Lamp (MIL). The Malfunction Indicator Lamp (MIL) may be intermittent and not be present at the time the vehicle comes in for service. Some technicians may find DTC U0265 sym00 That May Set As Current Or Failed In History in the K9 Body Control Module.
Cause	Engineering is currently investigating.

Correction

Note: For 2026 Blazer EV and 2025 - 2026 Equinox EV, please refer to 26-NA-080: Malfunction Indicator Lamp (MIL) DTC U0265 that May Set as Current or Failed in History.

For the remaining vehicles in this Preliminary Information, please read below:

Engineering is currently investigating.

Do not replace any parts including the K9 Body Control Module or the B174W Front View Camera - Windshield.

If vehicle comes in with ONLY the U0265 sym00 setting in the K9 BCM, clear the DTC and advise customer they may continue to drive the vehicle.

If vehicle comes in with other DTCs and with this U0265 sym00 setting in the K9 BCM, follow published Service Information diagnostics for the other DTCs and clear the U0265 sym00 after other diagnostics are performed and resolved.

The PI will be updated or replaced with TSB once a determination has been made.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information

Labor Operation	Description	Labor Time
2880578*	Verify DTC U0265 customers concern	0.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	5
Modified	09/19/2025 - Created on 01/12/2026 - Updated vehicle list. 02/16/2026 - Updated correction. 02/23/2026 - Updated correction. 05/06/2026 - Updated correction and model list.

