



Service Bulletin

Bulletin No.: PIT6455A

Date: May, 2026

PRELIMINARY INFORMATION

Subject: Service Driver Assist message with DTCs B1B2F and U1624

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2025-2026		All	All	All	All
GMC	Sierra 1500	2025-2026		All	All	All	All

Involved Region or Country	North America
Condition	A customer may comment that the Service Driver Assist message is displayed in the DIC. Dealer will find DTC B1B2F Telematics Control Module and U1624 Image Processing Control Module set current.
Cause	Software Anomaly

Correction

For 2025 Model Year vehicles an OTA has been released to correct this concern.

For 2026 Model Year vehicles, Engineering is currently investigating. In the meantime, please advise the customer to drive the vehicle. The PI will be updated or replaced with TSB once a determination has been made.

Version	2
Modified	11/20/2025 - Created on 05/04/2026 - Updated to the Correction section

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.