

Technical Service Bulletin (TSB)
Unable To Link Key FOB To Memory Profile

REFERENCE:	TSB: 08-209-26 GROUP: 08 - Electrical	Date:	May 7, 2026	REVISION:	–
VEHICLES AFFECTED:	2026 (WL) Jeep Grand Cherokee / Grand Cherokee L This bulletin applies to vehicles equipped with Driver Seat Memory (Sales Code LEQ).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers may experience the following: Customer is unable to link their Key FOB to the memory seat profiles using the published learning procedure in the Owner's Manual.				
CAUSE:	Software update				

DISCUSSION:

This Information Only bulletin contains information helpful or useful for technicians in diagnosing. This is a known software issue that will be later released to fix the issue. Do not replace the RFH, MSM, Key FOBs, or other related components.

NOTE: The current ETA for software is 4th quarter 2026.

POLICY:

Information Only.