

Bulletin Title Delivery Action D10366: Grid to High Voltage Converter A (GHCA) Replacement, Model Year 2026 EX90		Group 32	NO D10366
Issuer (Dept.) Product, Safety and Compliance	Car Market United States and Canada	Issue Date 3/27/26	Status Date 3/27/26
Revisions		Page Page 1 of 2	

- A. DELIVERY ACTION D10366 DESCRIPTION**
- B. VEHICLES INVOLVED**
- C. PORT VEHICLES (if applicable)**
- D. PARTS INFORMATION/PARTS RETURN if applicable**
- E. OWNER NOTIFICATION**
- F. VEHICLES IN RETAILER INVENTORY**
- G. RETAILER RESPONSIBILITY**
- H. TECHNICIAN COMPETENCY REQUIREMENT**
- I. CAMPAIGN REIMBURSEMENT PROCEDURES & RETAILER ALLOWANCE**

A. DELIVERY ACTION D10366 DESCRIPTION

Volvo Cars USA LLC and Volvo Cars Canada Ltd, on behalf of the Volvo Car Corporation, has decided to launch Delivery Action D10366: GHCA Replacement on certain Model Year 2026 EX90 vehicles.

Volvo Cars is requesting retailers to replace the GHCA on vehicles included in this delivery action prior to retail delivery.

The corrective action is to replace the GHCA according to VIDA.

B. VEHICLES INVOLVED

Model Years	Models Included
2026	EX90

The affected population consists of 26 Model Year 2026 vehicles in the United States only.

Vehicle eligibility must be confirmed by using TIE.

All vehicles must be checked for any incomplete recalls, service campaigns, or service upgrades, and all eligible repairs must be completed.

If you have any questions concerning this Quality Bulletin, please send them to recall@volvocars.com.

Quality Bulletin D10366

C. PORT VEHICLES

NOT all vehicles arriving from the ports may have been completed. It is the retailer's responsibility to check vehicle eligibility prior to delivery.

D. PARTS / PARTS RETURN

See parts bulletin D10366.

E. OWNER NOTIFICATION

Not applicable for this delivery action.

F. VEHICLES IN RETAILER INVENTORY

All vehicles marked for Delivery Action D10366 must be remedied prior to delivery.

G. RETAILER RESPONSIBILITY

All vehicles qualifying for this Delivery Action must be repaired prior to new car delivery.

H. TECHNICIAN COMPETENCY REQUIREMENT

The technician's competency requirement for this campaign repair is **G1 AND 1EV**.

I. REIMBURSEMENT PROCEDURES & RETAILER ALLOWANCE

Delivery Action D10366 claims should be submitted using the LONG FORM application only.

Claim Type: D10366
Cause Code: 02
CSC Code: XW
Main OP: 32301-2
Failed Part: **36000418**

Op No	Labor Time	Times/ Car	Main Op	Description	Competence Req
32301-2	.9	1	M	Battery charger, high voltage replace/ remove-install	G1
31130-2	.9	1		High Voltage Battery disconnection and connection	1EV
26151-3	.2	1		Cooling system electric powertrain, fill and bleed	G1
36002-3	.2	1		Software control module downloading	G1
36060-3	.1	1		Calibration with Vida	G1

***Labor times provided are current at the time of release and are subject to change: Claims will be paid at the time in effect on the repair date.**