



SIM 18 01 26

DISCOLORIZATION OF EXHAUST SYSTEM REAR SILENCER

2026-05-11

☐

THIS REPAIR IS MOBILE FRIENDLY


MODEL

U25 (Countryman S ALL4/JCW Countryman ALL4)

SITUATION

The rear silencer is discolored.

CAUSE



Tarnishing of the metal (1) on the rear silencer is caused by the heating and cooling of the exhaust.

CORRECTION

Inform the customer this is a normal occurrence when the metal of the exhaust system gets to operating temperatures.

It does not affect the functionality, or the durability of the exhaust system.

This is not rust/corrosion.

CLAIM INFORMATION

This Service Information Bulletin provides technical information.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

