

Technical Service Bulletin (TSB)
Flash: Electric Power Steering (EPS) Module Updates

REFERENCE:	TSB: 08-149-26 REV. A GROUP: 08 - Electrical	Date:	May 6, 2026	REVISION:	08-149-26
VEHICLES AFFECTED:	2026 (DT) RAM 1500 Pickup			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input checked="" type="checkbox"/> CH NOTE: This bulletin applies to the North and South America, Enlarged Europe, Middle East & Africa, India & Asia Pacific and China markets.	
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> Battery drain with ignition off. 				
CAUSE:	EPS Module Software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-149-26, date of issue April 15, 2026, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include converting this TSB to Information Only.

DISCUSSION:

NOTE: **The software required to perform this TSB is not available at this time.**

POLICY:

****Information Only****

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.