

REFERENCE:	TSB: 08-207-26 GROUP: 08 - Electrical	Date:	May 6, 2026	REVISION:	—	
VEHICLES AFFECTED:	<p>2022 - 2026 (D2) RAM 3500 Pickup 2022 - 2026 (DD) RAM 3500 Cab Chassis 2022 - 2023 (DF) RAM 3500 10K LB.Cab Chassis 2024 - 2026 (DJ) RAM 2500 Pickup 2022 - 2026 (DP) RAM 4500/5500 Cab Chassis 2022 - 2026 (DT) RAM 1500 Pickup 2026 (EJ) Jeep Recon 2024 - 2026 (JL) Jeep Wrangler 2025 - 2026 (KM) Jeep Cherokee / Wagoneer S 2024 - 2026 (LB) Dodge Charger 2022 - 2026 (MP) Jeep Compass 2021 - 2027 (RU) Chrysler Pacifica / Voyager 2022 - 2026 (VF) RAM Promaster 2022 - 2026 (WD) Dodge Durango 2023 - 2026 (WL) Jeep Grand Cherokee / Grand Cherokee L 2022 - 2026 (WS) Wagoneer / Grand Wagoneer</p> <p>This bulletin applies to vehicles equipped with one of the following radios:</p> <ul style="list-style-type: none"> • Uconnect 5 Nav W 8.4" Display (Sales Code UBL, UEL, or UFL) • Uconnect 5 W 10.1" Display (Sales Code UBG or UEG) • Uconnect 5 Nav W 10.1" Display (Sales Code UBN, UEN, or UFN) • Uconnect 5 Nav W 12.0" Display (Sales Code UBQ, UEQ, or UFQ) • Uconnect 5 W/ 12.3" Display (Sales Code UBP, UEP, or UFP) • Uconnect 5 Nav W 12.3" Display (Sales Code UBX, UEX, or UFX) • Uconnect 5 Nav W 14.4" Display (Sales Code UBW, UEW, or UFW) 			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America market.		
CUSTOMER SYMPTOM:	<p>The customer may experience flickering on their Instrument Panel Cluster (IPC) when the turn-by-turn feature is enabled. This issue occurs when using Google Maps for Navigation via CarPlay.</p>					
CAUSE:	<p>IPC Flickering</p>					

DISCUSSION:

This Information Only bulletin contains information helpful or useful for technicians understanding this only occurs with Carplay while using Google Maps for navigation and most likely to occur after updating PHONE to IOS 26.4.x (any version). A future IOS update version will bring improvement and currently has an eta of 2nd quarter 2026. Parts should not be replaced for this issue.

POLICY:

Information Only.