

Technical Service Bulletin (TSB)
Right Front Turn Signal Inoperable

REFERENCE:	TSB: 08-215-26 GROUP: 08 - Electrical	Date:	May 13, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on or after June 24, 2025 (MDH 0624XX) and on or before June 30, 2025 (MDH 0630XX).	MARKET APPLICABILITY:		<input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America markets.	
CUSTOMER SYMPTOM:	Customers may comment on one or more of the following: <ul style="list-style-type: none"> • Right front turn signal inoperable. • "Right Front Turn Signal Light Out" message in the Instrument Panel Cluster (IPC) Fig. 1. 				
CAUSE:	Manufacturing issue				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-088, date of issue May 13, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.




Fig. 1
IPC Message

REPAIR SUMMARY:

This bulletin involves inspecting and possibly replacing the right front turn signal bulb.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-50-52-91	Bulb, Park/Turn Signal - Inspect Right Front (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
08-50-52-92	Bulb, Park/Turn Signal - Inspect and Replace Right Front (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	L0007444NA	Park and Turn Signal Bulb	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Is the right front turn signal inoperable?
 - YES >>> Proceed to [Step 2](#).
 - NO >>> Use Inspect LOP (08-50-52-91) to close the active RSU.

NOTE: The turn signal bulb can be accessed from the engine compartment.
2. Open the hood.
3. Replace the turn signal bulb. Refer to the detailed procedures available in DealerCONNECT > Service Library > under: 08 - Electrical / 8L - Lamps and Lighting / Lamps/Lighting - Exterior / Lamp, Park and Turn Signal / Removal and Installation.
4. Close the hood.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.