



Service Bulletin

Bulletin No.: PIP6076A

Date: May, 2026

PRELIMINARY INFORMATION

Subject: Transmission fluid life will not stay at 100%

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------|-------------|----|------|-----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Corvette | 2024-2026 | | All | All | All | All |

| | |
|-----------------------------------|--|
| Involved Region or Country | North America |
| Condition | When performing transmission oil life reset, on the subsequent ignition or drive cycle(s) the percentage may drop much more quickly than expected, even to low values. |
| Cause | Currently under investigation with G.M. Engineering. |

Correction

Engineering is currently investigating. In the meantime, please advise customer they may continue to drive the vehicle.

This PI will be updated or replaced with TSB once a determination has been made.

| | |
|-----------------|--|
| Version | 2 |
| Modified | 06/27/2025 Created on. 05/18/2026 Added 2026 Model Year |

