



Service Bulletin

Bulletin No.: PIC6652

Date: May, 2026

PRELIMINARY INFORMATION

Subject: Sunroof or Sunshade Does Not Move, Grinding or Clunk Noise Heard When Trying To Move or Calibrate The Sunroof or Sunshade After Motor Replacement

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	LYRIQ	2023-2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	CAJ - PANORAMIC DUAL PANE SUNROOF WITH POWER SHADE CFD - ROOF - SUN, SINGLE GLASS, FIXED, ELEC SUNSHADE
Condition	After replacement of a Sunroof or Sunshade Motor, it may be found that there is a clunk or grind noise heard and the roof/shade does not move.
Cause	The Spring Plate may not have been transferred from original motor to new motor.

Correction

Ensure the Spring Plate was transferred to the new motor.

The Spring Plate will remain attached to the original motor when removed.

See picture below:



7136034

Version	1
Modified	05/20/2026 Created on

