



Service Bulletin

Bulletin No.: PIT6516B

Date: May, 2026

PRELIMINARY INFORMATION

Subject: K172 Night Vision Camera TAC Restriction

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|----------|-----------------|-------------|----|------|-----|---------|---------------|
| | | from | to | from | to | | |
| Cadillac | Escalade | 2021-2026 | | ALL | ALL | ALL | ALL |
| Cadillac | Escalade ESV | 2021-2026 | | ALL | ALL | ALL | ALL |
| Cadillac | ESCALADE IQ | 2025-2026 | | ALL | ALL | ALL | ALL |
| Cadillac | ESCALADE IQL | 2026 | | ALL | ALL | ALL | ALL |
| Cadillac | VISTIQ | 2026 | | ALL | ALL | ALL | ALL |
| GMC | Yukon | 2025-2026 | | ALL | ALL | ALL | ALL |
| GMC | Yukon XL | 2025-2026 | | ALL | ALL | ALL | ALL |

| | |
|-----------------------------------|--|
| Involved Region or Country | North America |
| Additional Options (RPO) | UV3 |
| Condition | As part of our ongoing quality improvement efforts and to ensure the Night Vision Camera replacement is necessary, the K172 Night Vision Camera has been placed on a part restriction through TAC. |
| Cause | A part restriction has been issued due to unnecessary part replacements. |

Correction

The vehicles listed above are subject to restriction, which will be managed by the GM Technical Assistance Center (TAC).

To proceed, the technician must provide detailed information, including customer comments, vehicle conditions, diagnostic trouble codes (DTCs), and any other relevant details. Pictures of the front fascia, lower air dam, and camera should be attached to the TAC case. For ease of diagnosis, please review DTC with GDS and attach the session log to the TAC case when created.

To request a K172 Night Vision Camera, dealerships are required to contact Technical Assistance (TAC).

U.S. Dealers:

Please contact GM Technical assistance (TAC) by opening a TAC CXC (CX Connect) Case in Global Connect, click on "New TAC Case" found on the Technical Assistance tab.

Canadian Dealers:

Please call 1-800-263-7740 for English or 1-800-263-7960 for French.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information

| Labor Operation | Description | Labor Time |
|-----------------|---------------------------------|--------------------------|
| 3450020 | Night Vision Camera Replacement | Use Published Labor Time |

| | |
|-----------------|--|
| Version | 3 |
| Modified | 05/08/2026- Created on 05/13/26- Updated models 05/20/26- Updated to add changes to correction field |

