

Transmission Oil Cooler Lines Rubbing APU Coolant Lines

COMMUNICATION:

FIELD SOLUTION: Fix as Fail

PUBLISH DATE:N/A

TOPIC BACKGROUND:


PRIMARY EFFECT:

- Nylon Transmission oil cooler lines if not fastened correct can rub & chafe & eventually leak at low mileage. If caught early, lines are replaced. If not caught quickly the entire transmission often must be replaced.

AFFECTED MODELS:

- Gen 5 Cascadia WST 47x 49x

VISUALIZATION:



PROGRESS UPDATES:

- Plant Work instruction was updated to address the routing requirements, Stating not to deviate or add any extra ties or clamps.
- Re-Training at the plants per the updated work instruction implemented & ongoing.

TOPIC RESOLUTION

PRODUCTION CHANGEOVER WEEK/MONTH:

- N/A
- Current State Process Audit – Complete 7/25

RESOLUTION:

- LTCA Production – Plant Updates – Add Transmission Cooler lines to Standard Routing and Clipping Guidelines.
- Verification 30/60/90 Day process audits to be complete by 7/30/26