

E004 – SMART KEY BATTERY DRAIN

SERVICE ACTION



| | |
|-----------------|---|
| AFFECTED MODELS | 25-26MY Range Rover, Range Rover Sport, Range Rover Evoque, Discovery Sport and 26MY Range Rover Velar, Defender, Discovery and F-PACE. |
| VOLUME AFFECTED | US 3571 CAN 512 |
| REPAIR | <p>A concern has been identified on specific vehicles within the above vehicle range, where a printed circuit board fault within the smart key may be present. The printed circuit board fault can cause a smart key battery drain which affects the functionality of the smart key. Retailers are required to perform a voltage test of each smart key and those failing should be replaced.</p> <p>IMPORTANT – ALL KEYS MUST BE PRESENT WHEN PERFORMING THIS REPAIR.</p> |
| REPAIR TIME | 0.1-0.2hrs + DIDO |
| CAMPAIGN LAUNCH | This repair bulletin was published April 28 th , 2026 |
| NOTES | <p>Retailers are required to hold from sale, all affected vehicles in their inventory until the repair is completed. Sold vehicles should be repaired at the next service visit.</p> <p>All affected VINs are flagged in TOPIx, the warranty portal and retailer inventory reports are available in BBSS.</p> <p>IMPORTANT – ALL KEYS MUST BE PRESENT WHEN PERFORMING THIS REPAIR.</p> |