

JLRTB02112NASV3
TECHNICAL BULLETIN
19 MAY 2026



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This bulletin supersedes TSB JLRTB02112NASv2/2024 dated 25 JUL 2024, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

SECTION:

310-00

SUBJECT/CONCERN:

Fuel Vapor Smell in Passenger Compartment - RESCINDED

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Range Rover (LK)	2022-2023	000001-089538	Solihull	V8 T/C 4.4L Petrol
Range Rover Sport (L1)	2023	000001-157098	Solihull	V8 T/C 4.4L Petrol

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Range Rover (LK)	2022 Onwards	000001 Onwards	Solihull	INGENIUM I6 3.0L Petrol
Range Rover Sport (L1)	2023 Onwards	000001 Onwards	Solihull	INGENIUM I6 3.0L Petrol

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

This bulletin has been **RESCINDED** with immediate effect.

The content previously detailed in this bulletin has now been replaced by the JLRTB02149 bulletin.

CAUSE:

N/A

ACTION:

N/A